



NDAD


helping others to help themselves

Equipment Cleaning & Disinfecting Guide

Follow these steps to clean and disinfect equipment before returning to NDAD.


1. CLEAN EQUIPMENT

Use soap and water to thoroughly clean all parts of the equipment.



2. DISINFECT EQUIPMENT

- Mix bleach water solution (follow instructions on bleach label)
- Spray and/or wipe equipment with bleach water
- Let air dry for at least 6 minutes



Now the equipment is ready to return to NDAD!

3. CALL TO SCHEDULE AN APPOINTMENT TO RETURN EQUIPMENT

- Grand Forks: (701) 775-5577
- Minot: (701) 838-8414
- Fargo: (701) 281-8215
- Williston: (701) 774-0741